



THORNTON LABORATORIES TESTING & INSPECTION SERVICES, INC.

1145 E. Cass St, Tampa, FL 33602
Phone: 813-223-9702 Fax: 813-223-9332
WWW.THORNTONLAB.COM

22-Jan-2016
Page 1 of 1

Report For: Bob's Berries Farm
11501 Winn Road
Riverview, FL 33569
Attn: Bob Clemons

Sample Identification:

Water - Well - Irrigation Supply
Loc: Water Spigot on the Well
Sampled on 1/20/16 @ 1630 hrs.
Total Residual Chlorine: 2.5 mg/L

Date Received: 21-Jan-2016

Laboratory Number: 388413

CERTIFICATE OF ANALYSIS

| Method | Parameter | Result | Detection Limit- Units | Analysis Date / Analyst |
|------------|---------------------|--------|------------------------------|----------------------------|
| SM 9222 B. | Total Coliform (MF) | < 1 | 1CFU/100mL | 21-Jan-2016 / CG |
| SM 9222 D. | E. coli (MF) | < 1 | 1CFU/100mL | 21-Jan-2016 / CG |

THORNTON LABORATORIES
Steve Fickett, III